



# Motor Connection DIAGRAM


## Star Connection




## Delta Connection



## Thermistor (PTC)



## Anti Condensation Heaters



Motors must be wired by certified electricians and can be wired Delta or Star Delta dependent on the size of the motor. The motor name plate must be checked for confirmation before beginning to wire up the motor.